

REPORT OF PERIODIC THOROUGH EXAMINATION

Munich RE 



HSB Engineering Insurance

Policy: H9S086179

Previous Report: 220316-013-0027PL1

Site: 00001

Report Number: 080916-002-0028EC1

LOLP1

The Lifting Operations and Lifting Equipment Regulations 1998, Regulation 9(3).
 The Lifting Operations and Lifting Equipment Regulations (Northern Ireland) 1999, Regulation 9(3).
 The Safety, Health & Welfare at Work (General Application) Regulations 2007 S.I. No. 299.

Employer THE GALLEON LEISURE CENTRE

Address 99 Titchfield Street, Kilmarnock
 East Ayrshire, KA1 1QY

Were examinations in accordance with an examination scheme? No

(a) Defects found which give rise to imminent danger and require attention immediately.

(b) Defects found which could, in time, give rise to danger and require attention within the specified time period.

Sched No.	Plant Code	Item	SWL	Particulars of any defect
L0009	L30AHH	Wheelchair Lift S.No.:8233 Cama Locn.:Pool Area	See note	a) None b) None General: All motions tested. No apparent defects. (Lift should be isolated at key switch when not required for use). Note: Safe working load = 1 Person + Wheelchair to a maximum of 225 kg.
L0005	L33AHH	Mobile Elevating Work Platform S.No.:9361 Upright	See note	a) None b) None General: All motions and micro-switches: tested. Safety switches require to be tested on a regular basis. Second section guides showed wear - to replace, as necessary. Jacking legs, screw sections worn - to replace, as necessary. No other apparent defects. Note: Safe working load = 1 Person + Equipment to Maximum 300 lbs, at Maximum working height 24 Ft.
L0011	L73AHH	Personnel Hoist S.No.:406671 Invacare Locn.:First Aid Room	180 kg	a) None b) None General: Year of manufacture: 2006. Actuator No. 1426468. Seen fitted with spreader frame, Serial No. 570040010103. Karabiner load hook showing slight wear - consider replacement. No other apparent defects.
L0007	L73AHH	Personnel Hoist Pool Lift S.No.:93DA0245 Arjo	160 kg	a) None b) None General: Chair wheels to lubricate. Boom replaced: 2010, moved to new position: 2011. Treat corrosion at the base of post and boom fixings. No other apparent defects. Note: Safe working load = 1 Person + Wheelchair to a maximum of 225 kg.
L0012	L96AHH	Lifting Sling S.No.:114300 Locn.:First Aid Room	175 kg	a) None b) None General: No apparent defects. Year of manufacture: 2007


This is to certify that, on the date of examination the items described above were thoroughly examined and unless otherwise indicated, were safe to operate.

Date of Examination: 07 Sep 2016

Date of Last Examination: 10 Mar 2016

Inspecting Engineer: Mr R Chambers

Date of Next Examination: 07 Mar 2017

Signature: 

Qualification: Engineer Surveyor

HSB Engineering Insurance Services Limited
 Registered in England and Wales: 03010292,
 New London House, 6 London Street, London EC3R 7LP
 Registered as a branch in Ireland: 906105
 Telephone: 0845 345 5510

HSB Engineering Insurance Services Limited
 is accredited by the United Kingdom
 Accreditation Service

