

REPORT OF EXAMINATION OF SYSTEM OR PARTS THEREOF

Policy: H9S086179

Plant Code: B57G14

Previous Report: 230315-011-0025SB2

Site: 00001

Schedule: B0024


Report Number: 220316-010-0027PL1

WRITTEN SCHEME NUMBER: WS02

PS1

1. Name and address of owner	THE GALLEON LEISURE CENTRE 99 Titchfield Street, Kilmarnock East Ayrshire, KA1 1QY
2. Subject to written agreement under the relevant Schedule of the regulations	No
3. Location of systems and name of user if different from above	Plant Room
4. (a) System identification (b) Identification of part of system (c) Description of part of system	PS02S Whole Refrigerant Pressure System Sabroe Serial No.:- 37372 Plant No.:- CIRCUIT 1
5. Results of examination and condition of parts examined in accordance with Written Scheme of Examination	Working Examination Only No apparent defects at normal working pressure. Suitable for further service.
6. Repairs (if any) required in order to prevent imminent danger if none enter "None"	None
7. Defects (other than those specified at 6 above) which require attention if none enter "None"	None
8. (a) Safe operating limit (b) Change in safe operating limits and date by which required if none enter "None"	28 bar None
9. Change in written scheme if required if none enter "None"	None
Postponement (Section 9(7)) Name of Competent Person Name of Users Representative Date of Postponement Date of limit of Postponement * If none enter "None"	None
11. Other observations	Year of manufacture: 2013. Rated: 75 kW. Safety valves: Twin low pressure, rated 16.2 bar. High and low pressure cut-outs via electronic control circuit.

Certification :- I certify that the above system or parts thereof was examined in accordance with the Written Scheme of Examination and that the above is a true report of the result.

Inspecting Engineer: Mr. R. Chambers
Qualification: Engineer Surveyor
Signature: 

	Thorough	Working
Date of Examination:	---	10 Mar 2016
Date of Last Examination:	---	12 Mar 2015
Date of Next Examination:	30 Jun 2017	10 Apr 2017

REPORT OF EXAMINATION OF SYSTEM OR PARTS THEREOF

Policy: H9S086179

Plant Code: B57G14

Previous Report: 230315-012-00258B2

Site: 00001

Schedule: B0025


Report Number: 220316-011-0027PL1

WRITTEN SCHEME NUMBER: WS02

PS1

1. Name and address of owner	THE GALLEON LEISURE CENTRE 99 Titchfield Street, Kilmarnock East Ayrshire, KA1 1QY
2. Subject to written agreement under the relevant Schedule of the regulations	No
3. Location of systems and name of user if different from above	Plant Room
4. (a) System identification (b) Identification of part of system (c) Description of part of system	PS03S Whole Refrigerant Pressure System Sabroe Serial No.:- 37561 Plant No.:- CIRCUIT 2
5. Results of examination and condition of parts examined in accordance with Written Scheme of Examination	Working Examination Only No apparent defects at normal working pressure. Suitable for further service.
6. Repairs (if any) required in order to prevent imminent danger If none enter "None"	None
7. Defects (other than those specified at 6 above) which require attention If none enter "None"	None
8. (a) Safe operating limit (b) Change in safe operating limits and date by which required If none enter "None"	28 bar None
9. Change in written scheme if required If none enter "None"	None
10. Postponement (Section 9(7))* Name of Competent Person Name of Users Representative Date of Postponement Date of limit of Postponement * If none enter "None"	None
11. Other observations	Year of manufacture: 2013. Rated: 75 kW. Safety valves: Twin low pressure, rated 16.2 bar. High and low pressure cut-outs via electronic control circuit.

Certification :- I certify that the above system or parts thereof was examined in accordance with the Written Scheme of Examination and that the above is a true report of the result.

Inspecting Engineer: Mr. R. Chambers
Qualification: Engineer Surveyor
Signature: 

	Thorough	Working
Date of Examination:	---	10 Mar 2016
Date of Last Examination:	---	12 Mar 2015
Date of Next Examination:	30 Jun 2017	10 Apr 2017